

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

#### -- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.

The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

#### -- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.



VOLUME XVII . NUMBER 5 . MAY/JUNE 1999



#### 1998-99 MEMBERSHIP AT ALL TIME HIGH

Our membership is at an all time high of 610 members. We must be doing something right as each year our membership increases. Thanks to

all who sent in information. Your sharing of letters, photos, newspaper and magazine clippings are one of the reason we're doing so well.

It means that you enjoy being part of a worldwide group of people who are fascinated with Buick as a car, as a marque in auto-

motive history that is with us today, as a mode of transportation that we still keep repaired and running and who appreciate a good source of parts, technical information and above all, friendship.

This is the next to last issue of our 1998-1999 publishing year. Most subscriptions expire with

the next (July/August) issue. Check the envelope label to see if you need to renew.

To make it easier, there will be a self-addressed renewal envelope included with the next issue. You can renew for more than one year if you want by pay-

ing the one year rate times the number of years you want to renew.

Our overseas members may want to consider sending the \$40 renewal fee in cash to avoid paying for a US dollar check. So far I've never failed

to receive cash renewals. If you have an e-mail address, please include it and I will let you know your cash has arrived.

It must have created a flash back for some people when member Anthony Wright (#1192) flew into San Francisco as he had a friend pick


him up in a 1936 Buick. This photo could have been taken in the late '30's judging by the car, suitcase, dress of the men and the buildings.

This humorous cartoon appeared in the March, 1942 issue of Motor Age magazine shortly after the US entered World War II. It was a well

> known magazine for auto repair shop owners and mechanics.

Richard
Vaillancourt
(#1171) in Rhode
Island has a '37
Special that came
with a Marvel carburetor. (Most '37
Special's came with
the Stromberg AA-1).
The linkage is dif-





"He says the Government kired him to spray caterpillars!"



TORQUE TUBE



ferent so they don't directly interchange. However you **can** exchange a '35 or '36 Stromberg EE-1 for the '37 Marvel used on Specials. The Stromberg EE-1 exactly replaces the '37 Marvel

with no modifications. Thanks for the tip Richard.

Sam Mahle (#1187) in Clarion, PA restored the '37 Century Coupe he used in college over 30 years ago.

**NON-	-CUM GUIDE	MIX SIZE: PI	NT		
827J	BLUE	60.6 175K	CHROMABASE	BINDER	B3.ē
B05J	JET BLACK	19.4			
Bláj	MED FINE ALUM	16.5			
866J	RED VIOLET	10.0			
45305	FLOP CONTROL AGENT	8.6			
1508	LS WHITE	5.2			
150K	CHROMABASE BALANCER	225.7	VGC-LE	5.8 VOC-	P: 5.0

Unlike 1937, '38 Buicks had a choice of two colors for the rims, either body color or an optional color. The optional color for Botticelli Blue was Dante (fire engine) red.

> Anyone out there restoring a 1938 80C Phaeton? If so, the end latches that hold the top down and mount on each end of the windshield are the same

as the ones used on the 40-60 series cars. These are being reproduced by *Lauren Matley* (#46), Phone: (253) 630-2008 in Kent, WA.

The only difference in the center latch is an off-set mounting stud, and 1/8" difference in length. So Lauren will have a couple of center latches made-up for anyone needing a replacement. You couldn't have the old ones replated for the cost of these new stainless latches.

Lauren also writes: "As for modern paint formulas, I have been toying with an idea on that problem. The formulas I developed over 10 years ago are nearly obsolete in that most jobs are acrylic ure-

He painted his car #504 Sudan (light) Blue. He has received many compliments on this color. He used DuPont ChromaBase BM487KH 1. Above is its formula. The rims (wheels)

were also be painted this color as there was not an optional wheel color in 1937. For Buick in 1937 wheels and body were painted the same color. 1938 Buicks offered the customer body color wheels or an alternate color.

Sam painted the Century himself using this type of Base-coat, Clear-coat. He found it easy to work with. It took him about a day to paint. Then it was buffed out. Sam has had a lot of compliments on both the color and the car.

Sudan Blue was also used in 1938 where it was called #519 Botticelli Blue.

# =TORQUE TUBE=

You can now find your '37-'38 Buick Club on the World Wide Web: http://www.classicar.com/clubs/buick/buick.htm

The **TORQUE TUBE** is published every two months for the enjoyment of the **1937-1938 Buick Club**. Membership dues are \$34.00 per year US, \$35.00 per year Canada or Mexico and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the **1937-1938 Buick Club**.

Please send all articles, ads subscriptions and inquires, etc. to:

The TORQUE TUBE 1005 RILMA LANE LOS ALTOS, CA 94022 USA

You can reach Harry Logan by PHONE/FAX (650) 941-4587 or by E-mail: harrylogan@earthlink.net

Editor:......Harry Logan, #651
Art Director:.....Dug Waggoner, #10

Printer Liaison:.....Bill Olson, #427
Printer:.....Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE

thane. Since I have a pristine 1937 Buick showroom color book and fabric swatches, a slightly different approach could assist all members. These color chip samples are 4 1/2" X 11", mounted on

hard felt and covered with a bonded clear cover, a computer scan would render very close matches."

"In using the computerized spectrophotometer, it can retrieve a standard formula by make, model, code number, and alternate shade. This could eliminate the problem for those who want to use a preferred brand of paint. This is the best of all solutions.

standard formulas very nearly perfect duplicates to the originals, available in any brand, type or quantity. This would be especially helpful to those

overseas members."

"As you know, some 1937 colors were used in 1938, with the only difference in the code number and the color name. So these formulas

would cover not only all of '37, but some of '38 as well. The problem is taking the time to accomplish this task. It is something that I hope to do in the near future."

Restoration Supply Company, phone: (775) 825-5663 in Reno. NV sells a couple of items members may be interested in. Both are imported from Australia.

One is Penrite Steering Box Lube (photo on page 2). It's about a 1200W oil which will not run out of your steering box. It doesn't pour or run but always stays in contact with the gears. This is one of the best lube's for all non-power steering boxes. It's also good for en-

closed U-joints and other parts which require a very think, sticky lubricant. It comes in a 500 ml bottle (about 1 pint). Part no. LUB009/\$7.50.

Restoration Supply also sells halogen headlight bulbs. They are much brighter than the original bulbs and have a standard pre-focus base

> to fit directly into original sockets of American cars, trucks and motorcycles. The 6 volt headlight is Part No. ELE 135/\$14.95 each. I have them installed in my '38 Century coupe. They definitely are brighter than the original bulbs. But I haven't used them enough to see how long they last or if the increased current damages the light switch.

> > Don Micheletti

(#250) reports he bought a door latch spring from them and that they were very nice to deal with. Be sure to ask for their catalog.


Take a look at this 1938 advertisment showing a "Heat Genie" arising from the engine compartment of a '38 Buick. It was promoting Gunk,

> a garage and chassis degreaser which you can still find on the market today.

New member John Wilson (#1406) is our first member from the state of West Virginia. He suggests members selling parts or cars include their e-mail address along with their address and phone number. That would make it less expensive to contact them.

Bill Shipman (#617) in Seattle, WA commented on the Adding Sidemounts article that appeared on pages 19 & 19 of the September/October. 1998 Torque Tube, Bill writes: "Sidemounted

Buicks had somewhat heavier front springs than their plain counterparts. I don't think the difference is critical, but those converting should



HYDRO.DEGREASING

Used Cars for Quick Resale

MUCH FASTER THAN STEAM CLEANING

TE MOTOR BLOCK IS WARM

LIST PRICE

53.00

Spray It On . . . Hose It Off!



consider the possible differences in handling characteristics and angle of repose, before making the switch without changing springs."

ED: I've noticed a slight downward tilt of the front of my 38-66S which has had the sidemounts added without changing the springs. Looking at the car from the side, you can see the nose is a little lower, but it's not very noticeable and does not effect handling. So I'll leave it as it is.

This photo above, of a black '38 Century coupe, belongs to Doug Nelson (#51) in Salem, Oregon. It's parked in front of an old garage that was moved there from his parents property. The red gas pump is a 1925 Red Crown.

Buick historian Terry Dunham would like to hear from anyone who owns or has seen a '37 or '38 Buick with only one sidemount. I have never seen one but heard there was a '38 Roadmaster in Southern California with only one sidemount. The cover car on the latest Buick Bugle magazine

shows a single sidemounted 1940 Century. Often factory dual sidemounted cars like my 38-61 are stamped with a "6" to indicate dual sidemounts. Does a single sidemounted car have a "5"? Let me know and I'll e-mail Terry. Thanks.

Long time member Al Lovi (#994) in California owns a '38 Century Sedan. He made these color car display posters, below, for my cars. He works from your photo and description of the car. I usually lean these framed posters against my front bumper. And people do stop and read them. Then they have a better appreciation for your car. Prices start @ \$50.00 and up depending on color, size and rendering of your car. You can contact Al at (707) 837-1786. Also

see his ad on page 30 of this issue.

Bob James (#371) in Canada has been selling 1936-1941 Buick parts for many years. He writes: "Through the years, I have collected quite a few manuals. catalogs, pictures etc. and would be willing



to share this information with fellow members." You can reach Bob at PO Box 531, Whitby, Ontario, Canada L1N 5V3. FAX: (905) 655-5310. Thanks for your offer Bob.

This black '37 McLaughlin Spe-

cial sidemounted sedan is owned by new member Mal O'Neill (#1425) in England. The car is very rare in the UK. It was fitted with a Lendrum & Hartmann (the UK Buich agents) division window behind the driver. It had two radios, one in the front for the chauffeur and one at the rear.




The first owner was the General Manager of the Radiant Sweet and Candy Company, Doncaster, England.

The next two photos, at the bottom of page 5, are a good examples of two of the sedan body styles for

1937 Buicks The trunk back was standard body configuration for styling but a new style was being shown for the first time.

The plain back, swept-back, slope back, fast back or stream lined style was added to the line that greatly enhanced the image of Buick in the



GM stable. Although the trunk was less spacious than that of the trunk back the spare tire was stored flat in the same sub-compartment.

The majority of the buyers favored the trunk back style models because of the increased luggage space which was noticeable in the production numbers between the two styles.

Andy Moreland (#1423) in Hamilton, New Zealand owns the first black 1937 Special 4-door sedan model 41. Andy says his Buick is in good condition, but needs a few bits and pieces replaced which he is slowly gathering. He takes his Buick out for a ride on most weekends.

The second black 1937 Special slant back 4door sedan belongs to new member Ed Kowalski (#1424) in Portage, PA. Ed needs some parts such as bumper guards and a center hood strip. Hopefully Ed will find them in one of our parts for sale ads.

This 1938 Special Model 41, below, has been sitting outside in New Zealand since 1978. The owner would not sell it, but after he died, his wife did. A collector bought it for a parts car. The body and chassis and rims are rusted. Even the coil springs. A few parts are salvageable and will find their way to a good home.

Here another 38-41 sedan project car at the top of page 7. Phil Mares (#1211) in Oklahoma

He has been working on it on and off for the past five years including putting in a new wooden shelf in the trunk.

The engine was removed from the car and rebuilt. Phil hopes to finish the car this year.


A book about 1935 Buicks has recently been published. The author will soon have books out on 1940 and 1941 Buicks. Next year he plans to do books on the 37/38 and 1953 Buicks. The author writes "The 1937/1938 Buick story is very interesting and probably, for the first time since it happened, it will reveal what really happened in the 1938 slump which was a case, not so much of reduced buying demand, but serious dealer cash flow problems."


The 1935 book costs \$15 including first class postage. If you're interested, they can be ordered from the author.

Walt Bruegger 1289 Magnolia St. #1 San Carlos, CA 94070 On the Comeback Trail









And that's what the 37/38 Buick Club is all about. As our motto says, we are An International Club for the Preservation and Restoration of all 1937 and 1938 Buicks!



Harry

## (Cover Cars)

The photos on our front and back covers show a black 1938 Century Sedan Model 61owned by *Mike Maroney* (#1226) in Southern California. Mike possess the most popular of the Century models and one of over twelve thousand Model 61's that Buick manufactured in 1938. See Mike's story below.

# THE RESTORATION OF A '38 CENTURY


By Mike Maroney (#1226)-Burbank, CA


This black 1938 Century sedan is our cover car. It originally came from the San Francisco area and once belonged to *Mike Edborg* (#167) in Fresno, CA. It was brought to the Los Angeles area around 1985 and I bought it in January, 1995. No restoration work had been done when I bought it. The car had never been in a car show since it had no interior. A new interior was installed. The engine was worked on and detailed.

The car had some body and paint work done


when it was in the San Francisco area. I had the front clip painted plus fixed all the mechanical problems. This took two years. The car now runs perfectly, like a rocket ship, and everything works.

The Pasadena B.C.A. car show was it's first time to be judged. To receive the first place award was a real accomplishment. Thanks for all the help and information I received from the *Torque Tube* and *our Club Members*. It's been a big help!





The car had never been in a car show since it had no interior but look at the finished product.





The engine had many areas worked on and finally detailed to what you see here. Ed: If there is one drawback to showing photos throughout the Torque Tube in black and white is that it does not match the beautiful color that Mike Maroneys pictures demonstrate. However, it does show a beautiful restoration.



# Eastern Meet

By Harry Logan (#651)-Los Altos, CA



The three day1999 Eastern Meet was held at this turn-of-the-century hotel and resort in French Lick, Indiana during the last week in May. We had a good turnout, about 45 people and sixteen 37/38 Buicks including three '37 Special Convertible Coupes. Plus on the first day, a '53 Buick, a '46 Dodge and a Plymouth sedan toured with us.



On Thursday we visited the Forest Discovery Center. The six acre building is large enough to contain thirteen football fields. It produces high quality moulding, trim and other wood products.



Afterwards, we had lunch on a farm, then drove to Kentucky to visit the Louisville Slugger Bat Factory and Museum. The entrance has an eye catching baseball bat, the world's largest.




Next, we stopped at Sherry and Paul Barger's home for a delicious barbecue lunch. Boy was it good!




Sherry (*left*) has attended several 37/38 meets with her friend *Archie Mitchell* (#946). They're seen in the rumble seat of *Clarence Hoffman*'s (#546) 37-46C.

Finally, on Saturday we toured the nearby West Baden Springs Hotel. Built in 1902 around a vast dome. The former hotel closed during the Depression and later served as a seminary and a private college. In 1998 the Indiana Historic Landmarks Foundation completed a restoration of the long-vacant National Historic Landmark.







We were awe-struck at the huge size of the free-standing dome, the wall design and columns and the huge marble floor.



Before heading home, some members posed with their cars on the hotel grounds. This is *Joe* and *Della Busby* (#846) from Anderson, IN and their 37-41.



Karl and Dorothy Anderson (#47) from Virginia have attended many 37/38 Meets in their 37-46C. They've even driven it to Oregon and back. They believe these cars were meant to be driven.



Karl even let several members drive his car. Here we see Steve King (#776) at the wheel, chauffeuring Jim Hackenburger (#1360) and Clarence Hoffman (#546) around town. The three day meet seemed to go by so fast. Now it's just a memory that I'll always remember!

#### THE WHEELS OF TIME

Named for Speed

# 1938 Buick Century Touri


amed for its ability to do an honest 100 mph, the Century was the smallest of the Buick line. behind the Roadmaster and Limited series. Many Buick historians consider the 1938 models the best of the prewar Buicks. From its tubular aluminum pistons in the straight-eight "Dynaflash" engine to its pioneering rear coil springs, the 1938 Buick was the choice of the upper-middle-class professional. Magazine ads extolled the car's ride and its "astounding" performance. In looks, the 1938 models were very similar to the 1937s with the exception of a new grille and front fenders. Options included a dual side-mounted spare tire that allowed more room in the trunk, an electric clock, a choice of two heaters, an electric windshield defroster and a center-line radio. Buick ranked fourth in sales in recession-wracked 1938, behind Chevrolet, Ford and Plymouth.

#### THE SPECS

Price	\$1,297
Engine	
Horsepower	141 at 3,600 rpm
Wheelbase	126 inches
Passenger capacity	


#### **HISTORICAL FACTS**

Year	18
President Franklin D. Rooseve	
Dow Jones industrial average (year-end) 154.7	6
Academy Award movie "You Can't Take It With You	u"
Milestone Eastern Airlines create	ed



Thanks to East Coast member Von Hardesty (#964) in Alexandria, Virginia for sharing this

# ng Sedan




clipping of a 1938 Buick Century Touring Sedan from the January 17, 1999 Washington Post.




By Harry Logan (#651)-Los Altos, CA

## 1937-1938 VOLTAGE REGULATORS



Original equipment for Buick in 1937-38 was a 5 terminal voltage regulator. If the original regulator became defective, the replacement was a 4 terminal regulator, P/N 1118213 (A).



The photo (**B**) shows that the last three digits of the part number (1118213) are stamped on the base of the regulator.

The manufacturers instructions (C) that came with it stated: "When replacing 5 terminal regulator, remove the regulator "IGN" terminal to ignition switch lead. If lead is in harness, cut off the lead as close to the harness as possible. Then tape the wire to the harness."

The 4 terminal regulator 1118213 was used on the following GM cars:

- Buick 1936 (Canadian cars).
- Buick 1937-1938 All Models.
- Chevrolet 1935


(State Police cars equipped with 936-N generators)


- Chevrolet 1936 (Canadian cars).
- Olds 6 & 8 1936
- . Pontiac 6 & 8 1936-1937
- Pontiac 8 1935-1938

In 1940, Buick used a higher output (and physically larger) regulator and generator. Some 37/38 Buicks have been converted to this system. The '40 generator is 8" long versus 7" for the 37/38. The regulator is larger (**D**) because it now includes a current regulator in addition to the voltage regulator and cutout relay used in 37/38.

So if you use a '40 or later generator, be sure to use the '40 and later, larger regulator containing three relays. Many replacement generator's carry the exchange number 62U on '40's, 60U on '37 and 52U on '38's instead of the Buick P/N.

This larger regulator means you cannot use both the firewall threaded regulator mounting holes. You will need to add one new mounting hole to the firewall to make the adjustment to the new wider '40 style regulator. The key message is not to mix a 37/38 regulator (#213) with the 1940 and later (longer) generator or you'll have problems.







The Nov./Dec. issue contained a question from a member who's having difficulty with cold starts: car starts easily when warm, but not after sitting for several days. Noticing that the butterfly valve in the carburetor air intake was not closed all the way with the engine cold, he wondered if this could be the problem; however, he said, he has no idea how to adjust the choke and doesn't have the special tools referred to in the shop manual. I doubt that the choke is at fault, and, in any event, nobody has those tools.

The butterfly valve should not close completely; if it did, the engine would flood. So long as it is partially closed, when the engine is cold and open all the way when the engine is hot, the choke is probably as good as it can get. It seldom pays to monkey with this choke; they are better left alone, and the only way to check its function. any more precisely than by eyeball, is to compare it with the choke on another car that runs well. If it's stuck, try cleaning; otherwise, my advice is: leave well enough alone.

Hard starting cold, especially after the car has been sitting for several days, is a common problem. The nature of the Stromberg carburetor is such that fuel drains out of it gradually when the engine is not running. After several days, the float chamber is empty and all the gas that was in it has gone into the intake manifold. The large engine has a drain valve in the manifold that allows this gas to drip out onto the ground-or the floor of your garage; the valve is closed by vacuum as soon as the engine starts. (This valve is worth a look now and then-if it's not closing, you've got a nice vacuum leak).

The Special engine does not have this valve. When you try to start the engine with an empty float chamber, the starter must turn the engine over until the mechanical fuel pump fills up the chamber.

Inasmuch as the starter is none too powerful, this may take some time, during which you are wearing out your starter and the teeth on the flywheel ring gear, and listening to that awful groaning. One cure is to have a reputable shop rebuild

## **ENGINE HARD** TO START?

By Bill Olson (#427)-Columbus, Ohio

your starter with "high-torque" windings; this will speed things up some.


A better cure, in my opinion, is to add an electric fuel pump. Six-volt pumps are readily-obtainable. They can be mounted anywhere in the fuel line between the tank and the mechanical pump. and wired up with a switch concealed under the instrument panel. The electric pump can push gas right through the mechanical pump; conversely, the mechanical pump can pull gas through the electric pump. It is therefore not necessary to run them together; indeed it is much better not to. The electric pump is used only for cold starts. Turn the electric fuel pump switch on; the pump will run for maybe 30 seconds and then stop. The float chamber is now full so switch off the electric fuel pump. At this point, using the normal procedure, she should start right up.


(Dug Waggoner (#10) - Lagree with Bill on these two improvements in starting a cold engine. Remember your carburetor wasn't designed to work with an electric fuel pump so make sure you buy one that is rated to work properly with your carburetor. There are some pumps on the market that you can adjust and fine tune the psi to the carburetor. It is also a good idea to tighten all the carburetor screws and mounting bolts or you could be pushing gas out of the carburetor and down onto the hot manifold. So if you do install an electric fuel pump make sure you check for leaks when you switch it on and always switch it off before you start your engine. When using the electric fuel pump you will find that this is also a good time to check for leaks in your mechanical fuel pump. If you find leaks there, it could rob you of acceleration and power because your sucking too much air through the feed line to the carburetor as well as contributing to the inefficiency of your mechanical fuel pump.

There is also a theory that says that if you encounter vapor lock, while you are driving, you can switch on the electric fuel pump to push gas through the fuel system to keep going to a safe, cool destination but remember to make sure you have no leaks in your carburetor or fuel system or you could have a barbecue before you get to the picnic. Safety First!)

# SERIES 40/60 Technical STEERING GEAR

From Motor Age magazine







Before making any adjustments to the steering gear, disconnect the drag link from the Pitman arm. You may need a forked tool called a Tie-rod Separator. Be sure to do the adjustments in this order:

#### 1. To remove the Pitman Shaft End Play:

- A. Tighten side cover bolts.
- B. Loosen lock nut "A."
- C. Turn screw "B" clockwise just enough to remove end play. Test by holding Pitman arm at the shaft and shaking in and out of steering housing.
- D. Tighten lock nut "A."

#### 2. To remove Worm Shaft End Play:

- A. Tighten end cover bolts.
- B. Loosen nut "C" at lower end of gear.
- C. Turn screw "D" clockwise as far as possible without stiffening the action of the steering wheel when turned from extreme right to extreme left. Spring scale attached to rim of steering wheel should show not over 1 pound pull required to turn wheel through entire range.
- D. Tighten lock nut "C."

#### 3. To remove Backlash Between Worm and Roller:

- A. Locate front wheels in straight-ahead position and disconnect drag link.
- B. Tighten end cover bolts (except bolt "E").
- C. Loosen bolt "E" one-half turn only.
- D.With soft hammer, tap lightly on lash adjuster "F" to turn it in direction of arrow. Move adjuster only 1/16 inch at a time, testing amount of back-lash each time by shaking Pitman arm fore and aft. Turn adjuster just enough to remove backlash.
- E. Tighten bolt "E."
- F. Connect drag link.
- G. Check backlash by turning steering wheel. There should be no lost motion when wheels are straight ahead.



By Harry Logan (#651)-Los Altos, CA

The U-joint is enclosed by the torque ball and is lubricated automatically from the trans-

mission. The front yoke of the U-joint is attached to the transmission mainshaft by splines and is locked by a cap screw. The rear yoke of the U-joint is attached to the propeller shaft by splines and is supported in a bronze bushing in the torque ball. The parts are assembled in the order shown in this diagram (A).

(**B**) The torque ball (center) is held in place by the inner (left) and outer (right) retainers.


The factory specification for the fit between U-joint and torque ball's bronze bushing is .006" loose. If the bronze bushing is worn, it can allow oil to pass to the rear axle. (**C**) The worn bushing can be removed after taking out its lock pin.

Then a new bushing (**D**) is installed and locked in place. If you still experience leakage from the transmission to the rear axle, it may be due to torque tube misalignment. This can happen if the strut rods are incorrectly adjusted.


The torque ball flange is bolted to the torque tube using (**E**) four bolts on Specials, six bolts on Big Series cars.


The torque ball is moveable and slides between the

# THE UNIVERSAL JOINT (U-Joint)









inner and outer retainers as the car goes over bumps. The two retainers are stationary and


bolted to the rear of the transmission. On 1936 models, the outer retainer had a cork oil seal.


(F) On 1937 and 1938 models, a spring washer was added to maintain pressure on the cork seal. This added pressure helps prevent oil leaks and scoring of the torque ball.


(**G**) The spring washer is slightly cupped. Take a look at (**H**) on how it should be installed so that there is a gap between the inside diameter of

the washer and the edge of the retainer.

When working on the U-joint, you will need a Torque Ball Seal Kit. Check the Ad for Bob's Automoblia on page 31. These \$27 kits (TBK 343) contain a neoprene (instead of the original rubberized-cork) oil seal, shims and a small tube of silicone. Then follow the printed instructions for a leak-proof seal.







Dale Lang (#1417) PO Box 68088 Portland, OR 97268

Gary Catherwood (#1418) 1878 Mosset Court Coquitlam, BC V3J 7P1 Canada

Brian Armer (#1419) Lancaster road Pilling Preston, England PR3 6AE 38-41

Paul Cook (#1420) 17 Thorndike Rd. Wakefield, MA 01880 37-665

# New Members

Ira Malek (#1421) 105-30 Flatlands 2nd St. Brooklyn, NY 11236

Jeff Lateer (#1422) 2240 Tanger Court Union City, CA 94587 38-61

Andy Moreland (#1423) 1147 Victoria Road RD 4 Hamilton, New Zealand 37-41 Edward Kowalski (#1424) 1303 Gillespie Ave Portage, PA 15948 37-47

Mal Oneill (#1425) Auckland Park Bishop Auckland Durham Co. England DL14 8RJ 37-41

Donald Stewart (#1426) 6403 23rd St. Lubbock, TX 79407 38-41

Michael Capps (#1427) 3229 Lovers Land Dallas, TX 75225

# Parts FOR SALE

• 1937 & 1938 PARTS The following is just a portion of the parts available. Call with your needs.

1937 PARTS	Cutt with your necus.
40/60 Series rear brake cables, good condition	\$40 pair
Coupe taillight, no stanchon or T bar	
80/90 series trunk hinges	
Master and deluxe heaters	
Roadmaster rims	
Roadmaster axles	
Roadmaster front suspension,	
Coupe & 2 Dr. Sedan side stainless, complete sets	\$75
Century brake & clutch pedal assembly	\$35
Century radiator	\$75
Special radiator	\$75
Rear springs 40 & 60, good condition	
Radio delete plates	\$15
Small series throttle linkage	\$25
Big Series rocker assemblies	
Fender lights	\$65 pair
Trunk lights, complete	\$50
Tail lights with lenses, all series	\$50 pair
Wiper transmissions	\$50 pair
Special manifold	\$75
Throttle cable	\$20
Special transmission	\$100
Special splash pans	\$40 pair

(Parts For Sale continued from page 24)	
Century hood.	\$100
Headlight switch	\$20
Radio grilles	\$15
Wiper motors	\$15
Trunk hold-up arms	\$20
Sun visors	\$15
Bumpers	\$30 each
Bumper arms	\$15 each
Steering wheel	\$50
40 & 60 running board brackets	\$50 set
Buick creast badge for hood trim strip	
Gas pedal	
Small and large series generators	
Aux. speaker	
DeLuxe heater with defroster and dash vents	
Owner's Manual	
Horn button, vgc	
Large series transmission.	
• 1938 PARTS	
Radio, working	\$300
DeLuxe Heaters	
40/60 series front bumper, re-chromed, not perfect	
40 & 60 sedan trunk lid, no rust	
Breather tubes	
Trunk hold-up arms	
734Z starter with solenoid	
Horn button	
Special hood lettering	
Defroster ducts	
Wiper transmissions	
Rear license plate stand, bracket & light for sedan	
Tail lights, complete	
Throttle cable	
Special radiator	
Battery tray	
Generator	
Special manifold, complete	\$75
Special hood sides & tops	\$25 each
Grille, no cracks, minor pitting	
Century radiator	\$100
Special coupe window moldings	\$100
Cigarette lighter	
Century motor, rebuilt, complete with AAV-2 and new clutch	\$2500 firm
Rear muffler hanger, NOS	\$35
Grille, some pitting	\$100 pair
AAV-1 carburetor, complete	\$175
AAV-1 missing choke cable	\$125

\$50 each\$50\$250\$150\$450\$450\$200 pair\$20 each\$20\$150\$200 pair\$20 each\$30\$30
\$250\$150\$2,000\$450\$200 pair\$20 each\$30\$15
\$150\$2,000\$450\$50 pair\$200 pair\$20 each\$30\$15
\$150\$2,000\$450\$50 pair\$200 pair\$20 each\$30\$15
\$2,000 \$450 \$50 pair \$200 pair \$30 \$30 \$30 \$15
\$450\$50 pair\$200 pair\$20 each\$30\$20\$15
\$50 pair \$200 pair \$20 each \$30 \$20 \$15 \$15
\$50 pair \$200 pair \$20 each \$30 \$20 \$15 \$15
\$200 pair \$20 each \$30 \$20 \$15 \$15
\$20 each \$30 \$20 \$15 \$15
\$20 \$15 \$15
\$15 \$15 \$40
\$15
\$40
\$15 each
\$50
\$10 each
\$20 pair
\$20 each
\$75 pair
\$25 pair
and the second s
\$50 pair
\$15
\$35 \$50 each
\$35 each
\$50
\$35
\$25
\$10 each
\$100 pair
\$75
\$50
\$100
or will part out
\$1,200 pair
6200
\$200 00 plus shipping

(Parts For Sale continued from page 26)	
• 1938 PARTS	
Engine (60-80-90)	
Rear end gears (4.18 ratio), 60-80-90	\$250
Transmission (60-80-90)	\$225
• 1937/38 PARTS	
Front rebuilt wheel cylinders (1-1/4") 80-90	\$130 se
Rear rebuilt wheel cylinders (1-3/16") 80-90	\$130 se
Front break drums (80-90)	\$\$75 se
Rear break drums (80-90)	
Front shocks (80-90)	
Front axles (80-90)	\$45 se
Front A-frames with lower control arm shafts (80-90)	\$75 se
David Bylsma (#117) 7802 Chevalier Ct.	
Severn, MD 21144	
(410) 551-7236	
• 1937 PARTS	
1937 Bottle Shaped Original Jack with Folding Handle	
Show quality. Detailed in Semi-gloss black	\$130 postpaid
Lewis Cohen (#584)	11
58 North Racebrook Rd	
Woodbridge, CT 06525	
• 1937/38 PARTS  1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact	d condition
• 1937/38 PARTS  1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK 0Z0  (403) 655-2251	d condition \$80
(203) 397-8723  • 1937/38 PARTS  1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada T0K 0Z0  (403) 655-2251	d condition \$80
• 1937/38 PARTS  1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK 0Z0  (403) 655-2251  • 1938 PARTS & LITERATURE FOR SALE	d condition \$80
(203) 397-8723  1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK 0Z0  (403) 655-2251  1938 PARTS & LITERATURE FOR SALE  Marvel CD-1B carburetor, rebuilt, Series 40	d condition \$80
(203) 397-8723  1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact Bruce von Zuben Sr. Box 745 Grassy Lake, Alberta Canada TOK 0Z0 (403) 655-2251  1938 PARTS & LITERATURE FOR SALE Marvel CD-1B carburetor, rebuilt, Series 40 Colored folder showing all series cars and new features	d condition \$8
(203) 397-8723  1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact	d condition \$8
(203) 397-8723  1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK 0Z0  (403) 655-2251  1938 PARTS & LITERATURE FOR SALE  Marvel CD-1B carburetor, rebuilt, Series 40  Colored folder showing all series cars and new features  Radio installation manual, reprint	d condition \$8
(203) 397-8723  1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact Bruce von Zuben Sr. Box 745 Grassy Lake, Alberta Canada TOK 0Z0 (403) 655-2251  1938 PARTS & LITERATURE FOR SALE Marvel CD-1B carburetor, rebuilt, Series 40 Colored folder showing all series cars and new features Radio installation manual, reprint All prices plus shipping John Johnson (#697)	d condition \$8
(203) 397-8723  1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK 0Z0  (403) 655-2251  1938 PARTS & LITERATURE FOR SALE  Marvel CD-1B carburetor, rebuilt, Series 40  Colored folder showing all series cars and new features  Radio installation manual, reprint  All prices plus shipping  John Johnson (#697)  276 N. Seymour Ave.	d condition \$8
(203) 397-8723  1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK 0Z0  (403) 655-2251  1938 PARTS & LITERATURE FOR SALE  Marvel CD-1B carburetor, rebuilt, Series 40  Colored folder showing all series cars and new features  Radio installation manual, reprint  All prices plus shipping  John Johnson (#697)  276 N. Seymour Ave.  Mondelein, IL 60060	d condition \$80
(203) 397-8723  1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact	d condition
(203) 397-8723  1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK 0Z0  (403) 655-2251  1938 PARTS & LITERATURE FOR SALE  Marvel CD-1B carburetor, rebuilt, Series 40  Colored folder showing all series cars and new features  Radio installation manual, reprint  All prices plus shipping  John Johnson (#697)  276 N. Seymour Ave.  Mondelein, IL 60060  (847) 566-5005	d condition
1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK 0Z0  (403) 655-2251  1938 PARTS & LITERATURE FOR SALE  Marvel CD-1B carburetor, rebuilt, Series 40  Colored folder showing all series cars and new features  Radio installation manual, reprint  All prices plus shipping  John Johnson (#697)  276 N. Seymour Ave.  Mondelein, II. 60060  (847) 566-5005  1938 PARTS—1938 Series 40:  Left front fender, fair condition	d condition
1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK 0Z0  (403) 655-2251  1938 PARTS & LITERATURE FOR SALE  Marvel CD-1B carburetor, rebuilt, Series 40  Colored folder showing all series cars and new features  Radio installation manual, reprint  All prices plus shipping  John Johnson (#697)  276 N. Seymour Ave.  Mondelein, IL 60060  (847) 566-5005  1938 PARTS—1938 Series 40:  Left front fender, fair condition  Right front fender, good condition	stories
1937/38 PARTS 1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact Bruce von Zuben Sr. Box 745 Grassy Lake, Alberta Canada TOK 0Z0 (403) 655-2251  1938 PARTS & LITERATURE FOR SALE Marvel CD-1B carburetor, rebuilt, Series 40 Colored folder showing all series cars and new features Radio installation manual, reprint All prices plus shipping John Johnson (#697) 276 N. Seymour Ave. Mondelein, IL 60060 (847) 566-5005  1938 PARTS—1938 Series 40: Left front fender, fair condition Right front fender, good condition Right running board, repairable core	stondition \$80 \$100 \$30 \$100 \$50 \$50
• 1937/38 PARTS  1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK 0Z0  (403) 655-2251  • 1938 PARTS & LITERATURE FOR SALE  Marvel CD-1B carburetor, rebuilt, Series 40  Colored folder showing all series cars and new features  Radio installation manual, reprint  All prices plus shipping  John Johnson (#697)  276 N. Seymour Ave.  Mondelein, IL 60060  (847) 566-5005  • 1938 PARTS—1938 Series 40:  Left front fender, fair condition  Right front fender, good condition  Right running board, repairable core  Headlight switch	stoodition \$80
• 1937/38 PARTS  1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK 0Z0  (403) 655-2251  • 1938 PARTS & LITERATURE FOR SALE  Marvel CD-1B carburetor, rebuilt, Series 40  Colored folder showing all series cars and new features  Radio installation manual, reprint  All prices plus shipping  John Johnson (#697)  276 N. Seymour Ave.  Mondelein, IL 60060  (847) 566-5005  • 1938 PARTS—1938 Series 40:  Left front fender, fair condition  Right front fender, good condition  Right running board, repairable core  Headlight switch	stondition \$80 \$80 \$80 \$80 \$80 \$80 \$80 \$80 \$80 \$80
• 1937/38 PARTS  1937 or 1938 Right side running board for a SPECIAL. It is in goo with the stainless trim and rubber intact  Bruce von Zuben Sr.  Box 745  Grassy Lake, Alberta  Canada TOK OZO  (403) 655-2251  • 1938 PARTS & LITERATURE FOR SALE  Marvel CD-1B carburetor, rebuilt, Series 40  Colored folder showing all series cars and new features  Radio installation manual, reprint  All prices plus shipping  John Johnson (#697)  276 N. Seymour Ave.  Mondelein, IL 60060  (847) 566-5005  • 1938 PARTS—1938 Series 40:  Left front fender, fair condition  Right front fender, good condition  Right running board, repairable core	stondition \$80 \$80 \$80 \$80 \$80 \$80 \$80 \$80 \$80 \$80

(Parts For Sale continued from page 27)
All Prices Plus Shipping and Handling
Charles Wenger (#1278)
(410) 877-7150, after 6 p.m. EST

#### 1938 PARTS

(530) 622-4606 home (916) 537-5210 work

#### 1938 PARTS

# Gards WANTED

#### WANTED: 1938 PARTS

- 2-outside 1938 locking door handles in excellent condition.
   5 & 3/16 inches long from end of shaft to key entry.
- 2-outside 1938 locking door handles. Can be in poor condition so long as they have the keyed shaft. 5 inches long from end of shaft to key entry.
- · 4-nice 1938 bumper guards.

John Baine (#1090) RR 2 Bradford, Ontario Canada L3Z 2A5 (905) 775-2622

#### WANTED: 1937/38 PARTS

Special or Century convertible sedan top bows. All or part.
Also any literature on convertible tops.

Larry Landrith (#1311)
2407 Mormon Island Drive
El Dorado Hills, CA 95762
(916) 933-3327

#### WANTED: 1938 PARTS

Accessory front horseshoe grille guard.

Ralph Rodriguez (#1201)

PO Box 0425

La Mirada, CA 90637

(562) 902-6417

# Gars FOR SALE

#### FOR SALE: 1938 SPECIAL

4-Door Trunk Back Sedan. Not running. Engine free. Parts of restoration car. Located in New Jersey

\$2,500.00

Art Sommers (#464) (732) 938-2495 or (732) 364-8884 in New Jersey

#### FOR SALE: 1938 SPECIAL

Modified Sport Coupe Model 46S. Dual sidemounts, two fold-down opera seats. 425 nailhead with duce fours.

\$25,000.00

Butch Leonard (#1257) (541) 382-5202 in Bend, Oregon

#### FOR SALE: 1937 SPECIAL

1937 4-door trunk back sedan Model 41.

No sidemounts, solid original, runs OK. Needs restoration.

It was an advertising car for Bamburgers Lounge in Port Jervis, N.Y.

83000.00 obo

Ron Stimson (#939) 21453 Northwood Ave. Fairview Park, Ohio 44126

Phone: (440) 333-7494



## Extra! Extra!

#### Back Issues Still Available!

THE FOLLOWING BACK ISSUES ARE AVAILABLE FOR \$4.00 EACH POSTPAID.

- 1991-1992 Volume X Numbers 1 through 9
   1992-1993 Volume XI Numbers 6 and 7
- 1993-1994 Volume XII Numbers 2, 4, and 6
- \* 1994-1995 Volume XIII Numbers 2, 4, and 6
- · 1995-1996 Volume XIV Numbers 3 through 6
- 1996-1997 Volume XV Numbers 4 through 6
- 1997-1998 Volume XVI Numbers 1 through 6

Please make your checks payable to:

The 1937-1938 Buick Club, 1005 Rilma Lane, Los Altos, CA 94022 USA

#### ONE OF A KIND CAR DISPLAY POSTERS!

Beautiful, Descriptive, Framed Collector Car DISPLAY POSTERS

for Car Shows are my specialty.

These Hand Made Posters really add that
"SPECIAL TOUCH" when displayed next to your car.

Prices start at \$50.00 and up depending on

Color, Size and Rendering of your car.

Al Lovi (#994) ART DESIGN STUDIO 95 Brianne Circle, Windsor, CA 95492 (707) 837-1786

## **CONVERTIBLE SUN VISORS**



\$165.00 each

These are authentic visors. All parts are chrome plated.

#### **WALLACE WAMSLEY**

(619) 283-3063

4732 Bancroft Street #7, San Diego, California 92116

#### 1904-1965 BUICK RESEARCH SERVICE

More information and detail about your specific 1937 or 1938 Buick year, model and serial number than you can get from any other source. SATISFACTION GUARANTEED.

Complete Research Package \$50.00, \$60.00 if shipped outside the USA.

Additional information available upon request, or send year, model, serial number, engine number, car photo (if available) and Fisher Body data plate rubbing.

#### 1937 BUICK HIGH QUALITY VIDEO

1937 Buick video made from the only known copy of a 16 mm black & white sound film produced by Buick Motor Division in 1937. The tapes have been made by a professional video dubbing studio. They are very high quality and are produced from a digitally mastered original. Video runs approximately 32 minutes and contains a number of segments showing the construction of the 1937 Buick and Buick's place in American society. Historically significant item. SATISFACTION GUARANTEED. \$39.95 including shipping.




## TERRY DUNHAM

Buich

P.O. Box 4057, Apopka, Florida 32704-4057 \* Phone 407-880-0797 \* e-mail: BUICKOHV@aol.com.

#### FRONT FLOORMAT 1937-38 All Models Black or Brown FF-378.....\$195.



## AUTOMOBILIA (805) 434-2963

#### 1937-38 BUICK



DOOR WEAT	HERSEAL-SPONGE	Ε.
Glue-in	DW-378	\$1.80 ft.
Clip-in	DW-80	\$3.25 ft.
Clips	WC-80	\$ .75 ea.
DOOR BOTTO	OM SEAL	



EXHAUST MANIFOLDS 1937-38 Series 60-80-90 ENDS \$185. CENTER \$189. VALVE BODY \$195.

			and the second second second
	Clips	WC-80	\$ .75 ea.
1	DOOR BO	OTTOM SEAL	
	Clip Ty	peDW-369	\$2.25 ft
1	TRUNK S	EAL-SEDANS, 1/2' Wide	
	Ser. 80	-90TW-371	\$35.50
		s. 3/4" Wide;	



RUNNING BOARD INSULATORS, 1937-38

All Models. ALL NEW MATERIAL! 4 Needed Per Running Board. RI-378S .... Set of 8 .. \$180.00



Ser. 40-60......TW-371S.....\$37.50



HOOD REST PADS. 1937-38 6-8 Per Car.




1/2'x1'x16' TL-1129 ..... \$47.50






CLUTCH and BRAKE PEDALS Series 40-60 











PLASTIC DASH KNOBS DK-37(38) \$ 6.	
PLASTIC DOOR HANDLE and Window	
Winder RINGS . HE-37(38) \$ 6.	



1937 ONLY! ACCELERATOR PEDALS Series 40-60 Back..AP-37BK .....\$32.00 Brown......AP-37BN .....\$35.50








SHIFT BOOT, 1937-38 Series 40 Only! Black ..... \$ 9.25 Brown.....\$18.50 Series 80-90 Black ONLY.... \$ 8.50

DOOR SILLS; Trim To Fit



DOOR FERRULE INSTALATION TOOL. \$20. Refundable if Returned Within 30 Days. DF-TOOL .....\$29.



2-Door \$62/pr. 4Door \$93/set. GLOVE BOXES; \$27. ea.

> 1938 TRUNK HANDLE/LIGHT MOUNTING SEAL...... DH-381.....\$8.95



CARB. KITS:CARTER......CK-360C \$27.00 STROMBERG...... CK-37XS .\$27.50

PARKING LIGHT LENS...... \$18.00 ea

MOTOR MOUNT, FRONT. All Models ROUND PADS...... SP-338... \$10. pr. MOUNT......MM-347.. \$51, pr



TBK-343 .....\$27.00 VISOR "VANITY" MIRROR. VM-379 ..... \$27. ea.


TORQUE BALL SEAL KIT, All Models

TRUNK HINGES for 40-60. Chrome Plated \$150. pr.

LICENSE PLATE FRAMES. Chromed Brass LF-333P.....\$62. Pair FRONT END PARTS For 40-60 Series;









SOME OTHER ITEMS WE STOCK: BEARINGS. DECALS, ENGINE PAINT, DECALS, SHOP MANUALS, PARTS BOOKS, BODY BOOKS and MORE. SHIPPING; 10%. max.\$9. min. \$4. Prepaid. C.O.D. Add \$5.

BOB'S AUTOMOBILIA BOX 2119 ATASCADERO CA. 93423 TELEPHONE (805) 434-2963 .VISA- MASTERCARD-DISCOVER or C.O.D. CATALOG #45 \$5.00 - PHONE ORDERS - (Write For Catalog)

## BUICK

"Upholstery and Top Kits"

1932 1955

Since 1977 .. Hampton Coach has been producing only the finest quality Interior and Top products available for GM cars. We offer complete Interior Kits, Seat Upholstery, Tops and related accessories as well as "era" fabric by the yard...

Inquire Toll Free .... 1-888-388-8726

e-mail lbb-hc@greennet.net



Amesbury, MA 01913





Restoration and repairs that are correct and authentic.

"I know your Buick." Former Director of Long Island, NY Chapter now has fully equipped shop in North Georgia. Ron Stanger, BCA #21079

Classic Car Works Ltd., 3050 Upper Bethany Rd. Jasper, GA 30143 Phone (770) 735-3945



## onaldson Co.

2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505

Beautifully Recast STEERING WHEELS

Thru 1953 Call or write for brochure



RESTORATION



SERVICES

Running Board / Rocker Moldings

1934 thru 1940

SSAE for Information

**BUICK RESTORATION SERVICES** 

P.O. BOX 442, PERRY,

MICHIGAN

48872



1927 TO

1953

## HARNESSES

**AUTHENTIC REPRODUCTION** WIRING SYSTEMS THRU 1953 HAND CRAFTED WITH THE FINEST MATERIALS EACH SUPPLIED WITH: LIMITED WARRANTY INSTALLATION INSTRUCTIONS SCHEMATICS

ALSO OFFERING: WIRING SUPPLIES CATALOG OR INFORMATION S5



BOX 435 WAYNE, PA. 19087 000

